

RECEIVING INSPECTION REPORT
HYCON MFG. COMPANY
2961 E. COLORADO ST., PASADENA, CALIF.

No. 11083

RECEIVED FROM

Plant #9

DATE REC'D. 1-29-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT
CODE NO.

DRAWING
NUMBER

DWG. DASH OR
STANDARD PART NO.

DWG.
REV.

LOT
NO.

CLASS
NUMBER

OPER
NUMBER

BUY OUT
CODE NO.

Q

ACCT. OR
W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED REJECTED

REMARKS

73154

QUANT

SHIP. TR #05987

RECEIVED
BY

INSPECTED
BY

Dma

DATE

11/30/57

REJECTS RETURNED

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11086

RECEIVED FROM

Lucas Aircraft Supply

DATE REC'D. 1-29-57

P.O. NO. 69209

VENDOR PACKING SLIP NO. 45045

CONTRACT
CODE NO.

DRAWING
NUMBER

DWG. DASH OR
STANDARD PART NO.

DWG.
REV.

LOT
NO.

CLASS
NUMBER

OPER
NUMBER

BUY OUT
CODE NO.

Q

ACCT. OR
W.O. NO.

S.O. NO.

CHARGE TO
QUANTITY
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED REJECTED

REMARKS

25

730133-00

Bolt 1/4 X 28 X 2 12/32 DIA-30

25

RECEIVED
BY

INSPECTED
BY

Dma

DATE

11/30/57

REJECTS RETURNED
ON SHIP. MEMO NO.